Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight *DHR Id#: 046-0092*

source Identification

Property Name(s): ..... Jones House {Historic}
Property Date: 1770
Address(s): ..... Route 626 {Current}
County/Independent City: Isle Of Wight
City: ....
State, Zip: .....Virginia
USGS Quad Name: ..... RUNNYMEADE

National Register Eligibility Status
Property is Historic (50 years or older)

Property has not been evaluated

Resource Description

Primary Resource Exterior Componant Description:

Component	Comp Type/Form	Material	Material Treatment
Chimneys	Chimneys - Exterior end	Brick	other
other	other	Wood	other
Foundation	Foundation - Solid	Brick	other
other	other	Wood	other
Roof	Roof - Gable	Asphalt	Roof - Shingle
Structural System	Structural System - Frame	Wood	Structural System - Weatherboard
Windows	Windows - Sash, double-hung	Wood	Windows - 6/9
Windows	Windows - Sash, double-hung	Wood	Windows - 4/4
Windows	Windows - Sash, double-hung	Wood	Windows - 6/6

WUZIT Count:

No.	Wuzit Types	Historic?
1	Barn	Historic
1	Single Dwelling	Historic
1	Poultry Shelter	Undetermined
1	Smoke/Meat House	Undetermined
1	Stable	Historic
1	Office/Office Bldg.	Historic

NR Resource Count:

Report generated 11/17/04

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight ***DHR Id#:*** **046-0092**

Individual Resource Information

WUZIT: ..... Office/Office Blog.

Est. Date of Construction: .... 1870 ca {VDHR Survey File} *Accessed?* .....

Primary Resource? ..... No *Number of Stories:* 0.0

Interior Plan Type: ..... *Threats to Resource:* .....

Description: Architecture Summary: Possibly an early office. End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: End Interior Description

WUZIT: ..... Stable

Est. Date of Construction: .... 1870 ca {VDHR Survey File} *Accessed?* .....

Primary Resource? ..... No *Number of Stories:* 0.0

Interior Plan Type: ..... *Threats to Resource:* .....

Description: Architecture Summary: End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: End Interior Description

WUZIT: ..... Smoke/Meat House

Primary Resource? ..... No *Number of Stories:* 0.0

Interior Plan Type: ..... *Threats to Resource:* .....

Description: Architecture Summary: Twentieth-century smokehouse. End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: End Interior Description

WUZIT: ..... Poultry Shelter

Primary Resource? ..... No *Number of Stories:* 0.0

Interior Plan Type: ..... *Threats to Resource:* .....

Description: Architecture Summary: Twentieth-century chicken coop. End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: End Interior Description

WUZIT: ..... Barn

Est. Date of Construction: .... 1860 pre {VDHR Survey File} *Accessed?* .....

Primary Resource? ..... No *Number of Stories:* 0.0

Interior Plan Type: ..... *Threats to Resource:* .....

Description: Architecture Summary: Antebellum barn. End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: End Interior Description

WUZIT: ..... Single Dwelling

Est. Date of Construction: .... 1770 ca {Site Visit} *Accessed?* ..... Yes

Primary Resource? ..... Yes *Number of Stories:* 1.5

Interior Plan Type: ..... Central Passage, Double Pile *Threats to Resource:* .....

Description: Architecture Summary: Three-bay, 1.5-story dwelling with molded box cornice with dentils. End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: End Interior Description

Cemetery Information

Bridge Information

National Register Eligibility Information (Intensive Level Survey)

Historic Context(s): ..... Architecture/Community Planning

Bibliographic Documentation

Ownership Information

Graphic Media Documentation

Medium	*Depository ID #*	*Photo Depository*	*Date*	*File Name*
B&W 35mm Photos	4:53		1978/3 /99	
B&W 35mm Photos	4:50		1978/3 /99	

Cultural Resource Management (CRM) Events

CRM Event # 1,
Cultural Resource Management Event: ... ... Intensive Survey
Date: ..... 978/3 /99
Organization or Person: ..... Dell Upton
CRM Event Notes or Comments: .....

VIRGINIA
HISTORIC LANDMARKS COMMISSION
SURVEY FORM

46-92
File Number

1. County ISLE OF WIGHT
   Town
   Street No. 626 (A)

   USGS Quad Name RUSHMERE
   Quad Date
   Original Owner
   Original Use
   Present Owner RICHARD NORMAN
   Present Owner Address VA. BEACH

   Present Use WORK IN PROGRESS

2. Historic Name JONES FARM
   Present Name
   Date or Period (exact or estimate) LATE 18C/LATE 18C-EARLY 19C/EARLY 19C
   Architect
   Builder, craftsman, etc.
   Source of Name
   Source of Date ARCH.

3. No. stories (dormers count as ½ story): 1½
   Wall construction FRAME
   Acreage 3

4. Historical Significance (Chain of Title, Families and Events, etc., connected with the property)

5. Architectural Significance (Note interesting interior and exterior details, etc., cite significant alterations and additions)

6. Physical Condition

	Excellent	Good	Fair	Poor
Structure		✓		
Grounds		✓		
Neighborhood	✓			

7. State potential threats to preservation of structure

(over)

3.4.78 JONES HOUSE (46-92), RT. 626, ISLE OF WIGHT Co.

RICHARD NORMAN — RUNNYMEDE 7.5
3 ACRES
VIRGINIA BEACH, VA — STEED XVI

EXTERIOR: NORTH: ORIGINAL FRONT — MOLDED BOX CORNICE 3 gabled (6/6) dormers w/ BEADED HOR BD TYMPANI, BEADED DIAGONAL BOARD CHEEKS — 6/9 SASH — 6P RP DR (OUOLO SR, QUIRK P) — EAST: 3 C AM CHIMNEYS w/ STEPPED WEATHERINGS — RODDED/PLAIN JOINTS — PENCILED JOINTS — REM. # S: PRESENT FRONT — ZOC MODILLION CORNICE — ORIG. CORNICE STOP — DORMERS AS OTHER SIDE — DBL 5 HORIZONTAL ◇ GRILLES — 3 C AM U.P. w/ RODDED JOINTS — BD WEBS — WEST: AS — STACKS REBLT IN PRESSED BRICK AFTER HURRICANE HAZEL — ZOC ELL REMOVED 2S

CELLAR: HALF CELLAR

INTERIOR: RM. A: 19⁴ x 15⁵/25⁵ — ORIGINAL ROOM — BEADED JOISTS ORIGINALLY EXPOSED — PRESENTLY SHEATHED IN PLAIN HORIZONTAL BOARDS — CHAIR RAIL + NAIL RAIL — LATE GEORGIAN MANTEL — SEGMENTAL ARCH OVER PASSAGE — W: ORIGINAL STAIR LOCATION — BX: ORIGINAL WINDOW Y: ORIGINAL DOOR Z: ORIGINAL DOOR — V: 7° QTR 19C PARTITION, NOW REMOVED CIRT BEADED — SEGMENTAL FP, RED PAINTED SURROUND —

RM. B: 13⁵ x 15³ — 2D ADDITION — PEDESTAL CHAIR RAIL, FLUSH WAINSCOT

RM. C: 13' x 9⁸ FIRST ADDITION — WALLS PLASTERED — DB PEG BOARD — 6P RP DR AS FRONT — FLUSH WAINSCOT — PEDESTAL CHAIR RAIL — MTL AS (A) — HERRINGBONE FIREBACK —

RM. D: 13⁵ x 9⁸ — 2D ADDITION — SEGMENTAL FP — MTL AS A — HERRINGBONE FIREBACK

ISLE OF WIGHT
cfd

2D FLOOR c77

RM. E: 12⁹ x 19⁵ - BOARD CEILNG - 18C-TYPE MUNTINS ON ON WINDOWS

RM. F: 9³ x 19⁵ - DB CHAIRBOARD - BOARD CEILN G - BOARDS BEHIND KNEE-WALL & SEAM IN FLOOR & CEILING SHOW BOARDING HERE & IN RM (A) TO BE ORIGINAL - IN OLD STAIR WELL

RM. G: 10³ x 19⁵ - SASH AS in E -

ROOF: PITCH: 46°

RAFTERS: 3x4 PINE - 2' CTRS - MTP/MORTISED F - BOARD FP -

COLLARS: 3½x3 SLP

SOME OLD FP RAFTERS w/ WROUGHT NAILS USED TO FRAME IN DORMERS WHICH, THOUGH EARLY, POST DATE 3D BUILD



LATE 18C (A)
LATE 18C/EARLY 19C (C; LEANTO ROOF)
EARLY 19C (B, D; PRESENT ROOF, CHIMNEYS, U.P.)

dw 3.6.78

JONES NOOSO

(AS)